



Date

25-May

Base Remount Pricing

Remounted Module and Chassis	Dealer List Price	Sourcewell Discount	Sourcewell Contract Price
Type I - Ford F450 4x2 193" WB 7.3L Gas	\$ 173,202.06	5%	\$164,542
Type III - Ford E450 4x2 158" WB 7.3L Gas	\$ 125,727.48	5%	\$119,441

Base Remount Includes the Following

Required Remount Compliance (CAAS GVS 3.0, QVM, FMVSS, & AMD)
White Chassis (F350, E350, F550, Diesel, & 4x4 Available on Options Page)
Modular Body to Same Modular Body Remount and Mounting Pucks
Disconnect Mechanical, Electrical, and Medical Systems Between Chassis and Module
Lift Module from Chassis and Position to Allow Full Inspection of Under Structure
Inspect Exposed Structural Framing, Welds, Tie Down Braces and Gussets
Inspect Lighting (Ceiling Lights, Compartment Lights, Dome Lights, Attendant Lights, etc)
Inspect Warning System (Lights and Audible)
Inspect Electrical System (Controls, Outlets, Shorepower, Etc)
Inspect Door Hinges, Handles, Latches, and Pins
Inspect Medical Equipment/Systems (Suction, Oxygen, Cot Mount, Glove Holders, Etc)
Inspect HVAC System
Alignment
New Backup Alarm
New High Idle
New Ground Straps
New Undercoating
New Running Boards
Transfer Chassis Emergency Lighting
Transfer Audible Warning Equipment (Sirens and Air Horns)
Transfer Customer Radios
Transfer Chassis Center Console
Transfer Security Device Systems
Transfer Module Emergency Lighting
Transfer Door Mechanisms, Handles, Door Grabbers, and Pins
Transfer Electrical System
Transfer HVAC System
Transfer and Polish Diamond Plating, Module Corners, Kickplate, and Splash Guards
Transfer Fenderettes
Transfer Rub Rails
Transfer Rear Bumper
Transfer Backup Camera
Rear Liquid Springs (Type I)



Date 25-May

Optional Remount Pricing

The Following is a List of Options. Special Requests and Items Not on This List Available on Request.

Description	Dealer List Price	Sourcewell Discount	Sourcewell Contract Price
Chassis Specifications			
Upgrade to F550	\$ 650.00	5%	\$618
Add Diesel Motor	\$ 10,495.00	5%	\$9,970
Add 4x4	\$ 2,614.00	5%	\$2,483
Ram Chassis Available on Request	TBD	5%	TBD
Chevrolet Chassis Available on Request	TBD	5%	TBD
Medium Duty Available on Request	TBD	5%	TBD
Chassis Modifications			
Center Console	\$2,932	5%	\$2,786
Exterior Lighting	\$1,393	5%	\$1,324
Front Liquid Spring	\$16,125	5%	\$15,319
Appearance Modifications			
Module Repainted White (Includes Prep)	\$36,507	5%	\$34,682
Module Repainted Custom 2-Tone Color (Includes Prep)	\$40,841	5%	\$38,799
Chassis Repainted Custom Color (Includes Prep)	\$9,720	5%	\$9,234
Replace ADP Rub Rails	\$1,703	5%	\$1,618
Replace Rear Bumper	\$3,243	5%	\$3,081
Replace Rear Kickboard	\$604	5%	\$574
Replace Module Corners	\$459	5%	\$436
Replace Splash Guard	\$329	5%	\$313
Replace Drip Rails	\$537	5%	\$510
Replace Door Seals	\$833	5%	\$792
Blackout Package (Rims, Mod Corners, Steps, Bezels, Rub Rails, etc)	\$6,622	5%	\$6,290
Emergency Lighting			
Techniq Emergency Lighting	\$10,265	5%	\$9,751
Whelen Hundred Series Emergency Lighting	\$16,346	5%	\$15,528
Whelen M Series Emergency Lighting	\$19,320	5%	\$18,354
Tomar Emitter	\$1,646	5%	\$1,564
Audible Warning Equipment			
Whelen Siren Speakers	\$1,308	5%	\$1,243
Buell Air Horns	\$2,581	5%	\$2,452
EQ2B Siren	\$3,895	5%	\$3,700
CPI Siren Speakers	\$1,237	5%	\$1,175
Whelen Howler	\$1,641	5%	\$1,559
Electrical Modifications			
Replace Electrical System	\$11,909	5%	\$11,314
Add Electrical Outlet	\$437	5%	\$415
Replace Inverter	\$2,139	5%	\$2,032
HVAC Modifications			
Replace HVAC	\$3,609	5%	\$3,429
Replace HVAC with Front Mounted Condenser	\$5,170	5%	\$4,912
Exterior Handle Modifications			
Clean & Polish Compartment Door Panels	\$637	5%	\$605
Clean & Polish Door/Compartment Hinges - Repair Doors and Mounting points	\$719	5%	\$683
Clean & Polish Entry Door Panels	\$316	5%	\$300
Clean & Polish Compartment Interior	\$1,318	5%	\$1,252
Transfer and Clean Compartment and Entry Door Handles, Door Grabbers, Striker Bolts, Rods, and Components	\$2,136	5%	\$2,029
Replace Compartment and Entry Door Handles, Door Grabbers, Striker Bolts, Rods, and Components (TriMark Default)	\$6,226	5%	\$5,914
Interior Module Modifications			
Interior Refurbishment (Fill holes, replace broken trim, various repairs to enhance appearance. Assumes 8 hrs of labor and limited materials)	\$401	5%	\$381
Replace Cabinet Shocks	\$401	5%	\$381
Replace Lexan	\$1,872	5%	\$1,778
Replace Countertops	\$1,765	5%	\$1,676
Clean and Polish Floor	\$405	5%	\$385
Replace All Pads and Cushions	\$3,714	5%	\$3,528
Replace Attendant Seat	\$2,328	5%	\$2,212
Replace Door Thresholds	\$789	5%	\$750
Stryker Equipment Modifications			
Install New Universal Floorplate and Wiring	\$2,846	5%	\$2,703
Install Customer Supplied Powerload	\$516	5%	\$490
Install New MacQueen Supplied Powerload	\$39,629	5%	\$37,647